




MODELS




A30/A40




N30/N40





C40/C60




Type	A30/40	N30/40	C40	C60
S	●	●	●	●
P	●	●	●	—
G	●	●	●	●
R	●	●	●	●
L	●	●	●	●
Alpha (1)	●	●	●	●
Evolution (2)	●	●	●	●
R600A	—	●	●	●
NH ₃	●	—	—	—




DIMENSIONS




	A	B	C	D
A30	384 mm 15.1 in	446 mm 17.6 in	520 mm 20.5 in	356 mm 14.0 in
N30	384 mm 15.1 in	415 mm 16.3 in	520 mm 20.5 in	356 mm 14.0 in
A40	405 mm 15.9 in	466 mm 18.3 in	550 mm 21.7 in	376 mm 14.8 in
N40	405 mm 15.9 in	435 mm 17.1 in	550 mm 21.7 in	376 mm 14.8 in
C40	405 mm 15.9 in	481 mm 18.9 in	550 mm 21.7 in	376 mm 14.8 in
C60	490 mm 19.2 in	510 mm 20.0 in	565 mm 22.2 in	410 mm 16.1 in



Freestanding







AIR FLOW








Scan this QR code to watch a video about the impact of air flow.
<https://dreambroker.com/channel/zrzej1zj/w4v0sx10>

Insufficient air flow results in a shortened lifespan and a reduced cooling performance.
Observe the minimum spacings when installing the minibar to furniture.








AIR FLOW








	Air inlet	Air outlet
N30, N40	200 cm ² 31 sqin	200 cm ² 31 sqin
A30, A40, C40, C60	150 cm ² 23.25 sqin	200 cm ² 31 sqin


INSTALLATION NOTES






REVERSING DOOR




FIXING




SLIDING HINGE



SHELVES



DOOR LOCK



YOUR LOCAL DEALER
dometic.com/dealer

YOUR LOCAL SUPPORT
dometic.com/contact

YOUR LOCAL SALES OFFICE
dometic.com/sales-offices

A complete list of Dometic companies, which comprise the Dometic Group, can be found in the public filings of:
DOMETIC GROUP AB Hemvärmgatan 15 SE-17154 Solna Sweden